Firmware for EDS-405A Series (PTP models) Release Notes

Version: v3.8	Build: Build_17041115
Release Date: May 04, 2017	

Applicable Products

EDS-405A-PTP

Supported Operating Systems

N/A

New Features

N/A

Enhancements

• Add warning message when default password was not changed.
• Encrypt security keys in user interface.

Bugs Fixed

• Cross-site scripting vulnerability.
• Denial of Service attack vulnerability.
• Privilege escalation vulnerability.
• SSL v2/v3 vulnerability in HTTPS.
• Web console cannot be accessed due to SNMP get bulk.
• Specific CLI command caused switch to reboot with default settings.
• Adding a new VLAN changed IGMP querier state from disabled to enabled.
• Saving configurations to ABC-01 could not be performed via IE browser.
• Rate limit could not be set in web UI.
• Telnet hangs after SSH disabled.
• Correct RSTP edge definition in exported configuration file.
• Correct authorization of Radius/TACACS+ login.
• Correct RSTP Auto-Edge behavior.
• System could only reboot after a period of operation while PROFINET was enabled.
• After the firmware has been upgraded, the system sometimes performed a warm start when the user logged in to the switch.

Changes

N/A

Notes

N/A

Version: v3.5	Build: Build_15040918
Release Date: N/A	

Applicable Products

EDS-405A-PTP

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

• Ethernet ports auto-negotiation fail at 10 M speed.
• 1588 PTP time synchronization failed after rebooting grandmaster clock.
• Unable to configure system name via SNMP.

Changes

N/A

Notes

N/A

Version: v3.3	Build: N/A	
Release Date: N/A		

Applicable Products

EDS-405A-PTP

Supported Operating Systems

N/A

New Features

• First release for EDS-405A-PTP Series.

Enhancements

N/A

Bugs Fixed

N/A

Changes

N/A

Notes

N/A