Firmware for EDS-P510 Series Release Notes

Version: v3.8	Build: Build_17041115
Release Date: May 04, 2017	

Applicable Products

N/A

Supported Operating Systems

N/A

New Features

N/A

Enhancements

• Add warning message when default password was not changed
• Encrypt security Keys in user interface
• Enhance RSTP compatibility

Bugs Fixed

• Cross-site scripting vulnerability.
• Denial of Service attack vulnerability.
• Privilege escalation vulnerability.
• SSL v2/v3 vulnerability in https.
• Web console cannot be accessed due to SNMP get bulk.
• Specific CLI command cause switch reboot with default settings.
• Add a new VLAN will change IGMP querier state from disable to enable.
• Saving configuration to ABC-01 cannot be performed via IE browser.
• Rate limit cannot be set in web UI.
• Telnet hangs after SSH disabled.
• Correct RSTP edge definition in exported configuration file.
• Correct authorization of Radius/TACACS+ login.
• Correct RSTP Auto-Edge behavior.
• After upgrade firmware, the system maybe warm start when the user login the switch

Changes

N/A

Notes

N/A