Firmware for CN2510 Series (Rev. 3.x) Release Notes

Version: v3.1	Build: Build 07081513
Release Date: Dec 21, 2009	

Applicable Products

CN2510-8, CN2510-16, CN2610-8, CN2610-16

Supported Operating Systems

N/A

New Features

• Supports RedundantCOM function for CN2610-8/16.

Enhancements

N/A

Bugs Fixed

• RIP packet could not be sent out via PPP & SLIP. (RDC07989)
• AsyncServer's DHCP only sent DHCP requests twice. We modified the DHCP behavior; AsycServer will continue to send DHCP discover packets if there is no DHCP response. (RDC07971)
• AsyncServer would not save the sender's MAC address if the target IP was not my IP. (RDC07943)

Changes

N/A

Notes

N/A

Version: v3.0	Build: N/A
Release Date: N/A	

Applicable Products

CN2510-8, CN2510-16, CN2610-8, CN2610-16

Supported Operating Systems

N/A

New Features

• Supports MOXART CPU.

Enhancements

N/A

Bugs Fixed

• Fixed accepting uni-directional software flow control. (v2.1.15)
• Dial-in Mode TCP Compress enable issue. (v2.1.9)
• Dial-in/Dial-out Mode Packet Fragmentation problem. (v2.1.7)
• Direct cable connection issue for PPP mode. (v2.1.1)

Changes

• PPP Modification: Waits for client IPCP request first then sends out Server's ICPC Request. (v2.1.3)
• PPP Modification: Improved IPCP negotiation, if receiving a request for DNS IP "0.0.0.0/255.255.255.255". (v2.1.3)

Notes

N/A