



Firmware for UC-8100 Series Release Notes

Version: v2.1	Build: Build 17072510
Release Date: Jul 28, 2017	

Applicable Products

UC-8100 Series

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

N/A

Changes

- Updates bootloader to be compliant with new memory.

Notes

N/A



Version: v2.0	Build: Build 17062219
Release Date: Jul 24, 2017	

Applicable Products

UC-8100 Series

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

- Fixed CVE Issues:
CVE-2016-4482
CVE-2016-4486
CVE-2016-4805
CVE-2016-3138
CVE-2016-2550
CVE-2016-2847
CVE-2016-3134
CVE-2016-3156
CVE-2016-0723
CVE-2016-0821
CVE-2016-5696
CVE-2016-7117
CVE-2016-6828

Changes

- Upgrades root file system from Debian 7 to Debian 8. See <https://www.debian.org/distrib/packages.en.html>
- Upgrades Linux kernel from 3.2 to 4.1.36. See <https://www.kernel.org/pub/linux/kernel/v4.x/>
- Updates moxa-cellualr-utils, uc8100-system, uc8100-sysconfig, uc8100-syskernel packages.
- Updates moxa-cellular-utils to v1.19.0.
- Set some nouser and nogroup files to right attribute.
- Modified watchdog driver to fix 'ioctl could disable wdt in nowayout mode' issue.
- Moved mx_led_control tool from /bin folder to /sbin folder.
- Modified USB host driver to support "usb port control" feature by bootloader setting.
- Fixed the omap-sham warning message.
- Supports SD card write protect by bootloader setting.

Notes

N/A



Version: v1.7	Build: Build 17011120
Release Date: N/A	

Applicable Products

UC-8100 Series

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

- Fixed MC7354 "switch_carrier" Issue.

Changes

N/A

Notes

N/A



Version: v1.6	Build: Build 15110421
Release Date: N/A	

Applicable Products

UC-8100 Series

Supported Operating Systems

N/A

New Features

- Adds Yuga cellular module (Enable China LTE).
- Adds ftp-related driver (Enable ftp function).
- Adds a check sierra modules mtu size function.

Enhancements

- Upgrade package
 - Update uc8100-cellular-utils to version 1.6.0
 - Update uc8100-diag to version 1.2.0
 - Update uc8100-system to version 1.6.0

Bugs Fixed

- Fix chs_signal led bugs
- Fix PPPoE Connection Error of MC73xx

Changes

- Remove TPM tool related-functions in following files
 - mx_diag
- modified default domain name
- disable supports_autosuspend function for qmi_wwan driver
- Clear bash shell history command.

Notes

N/A



Version: v1.5	Build: Build 15090108
Release Date: N/A	

Applicable Products

UC-8100 Series

Supported Operating Systems

N/A

New Features

- Add bluetooth related kernel drivers.

Enhancements

- Upgrade package
 - Update openssl to version 1.0.1e-2+deb7u17
 - Update libqmi to version 1.12.6
 - Update cellular-utils to version 1.5.0
 - Update libssl to version 1.0.1e-2+deb7u17
 - Update apache2 to version 2.2.22-13+deb7u6
 - Update apache2-mpm-prefork to version 2.2.22-13+deb7u6
 - Update apache2-utils to version 2.2.22-13+deb7u6
 - Update apache2.2-bin to version 2.2.22-13+deb7u6
 - Update apache2.2-common to version 2.2.22-13+deb7u6
 - Update dpkg to version 1.16.16
 - Update file to version 5.11-2+deb7u8
 - Update mysql-common to version 5.5.44-0+deb7u1
 - Update libexpat1:armhf to version 2.1.0-1+deb7u2
 - Update libldap-2.4-2:armhf to version 2.4.31-2
 - Update libmagic1:armhf to version 5.11-2+deb7u8
 - Update libmysqlclient18:armhf to version 5.5.44-0+deb7u1
 - Update libsqlite3-0:armhf to version 3.7.13-1+deb7u2
 - Update libtasn1-3:armhf to version 2.13-2+deb7u2
 - Update libxml2:armhf to version 2.8.0+dfsg1-7+wheezy4
 - Update mysql-common to version 5.5.44-0+deb7u1
 - Update ntpdate to version 1:4.2.6.p5+dfsg-2+deb7u4
 - Update ppp to version 2.4.5-5.1+deb7u2
 - Update tzdata to version 2015e-0+deb7u1
 - Update wpasupplicant to version 1.0-3+deb7u2

Bugs Fixed

- Fix USB driver
 - fix IRQ race during initialization
 - fix tty-device error handling at probe
 - fix potential use after free
 - fix race in generic write
- Fix RS232-UART driver
 - fix UART data failed issue when disabling hardware flow control.

Changes

- Bootloader version: 1.3.0S03.
- Enables GobiSerial module: Makes GPS function more stable, automatically enables or disables



GPS, when the module device node is opened or closed.

- Removes TPM tool related-packages: libtpm-unseal1, tpm-tools, ousers, libopencryptoki0, opencryptoki, and libtspi1
- Removes TPM tool related-functions in following files: expand2fs and mx_uc8100.
- Upgrades RAM from 256 MB to 512 MB.

Notes

N/A



Version: v1.4	Build: Build 15032016
Release Date: N/A	

Applicable Products

UC-8100 Series

Supported Operating Systems

N/A

New Features

- Adds GRE related drivers.
- Adds the Sierra 3G/4G driver for IPv6.
- Adds the mangle driver.
- Adds the overlaysfs driver.

Enhancements

- Enhance cellular connection utility: Dial up/connect to cellular network, Soft-reset (restart) module, Hard-reset module, Check carrier, Choose carrier, Reset module to factory default, Send AT command, Set PIN code, SIM card status, and Enable/ Disable PIN of SIM card
- Support UART baudrate 921600.
- Patch Linux 3.2.66 wifi related files.
- Enhances watchdog function: Disable "NOWAYOUT" in default, enable "MAGIC CLOSE" in default, and provides configurable option on the module parameters "NOWAYOUT" and "TIMER_MARGIN".
- Enhances SD card compatibility with bootloader.

Bugs Fixed

- Security issues in OpenSSL, ntpdate, bash, glibc.
- RS-232 data loss issue.
- Network driver issue
- Serial Number length to 12 byte in bootloader.

Changes

- Adds Black Gobi-related driver in default settings.
- All LEDs except power LED turn off when the system halts.
- Adds /etc/modprobe.d/watchdog.conf.
- Initializes the GPIO PIN for UART earlier to avoid "setinterface" fail in rc.local.
- Bootloader version: 1.2.0S02.
- Blinks the LED after stopping 8100 services.
- Switch the SD/USB LED control behavior to the user space, so as to enable specifying the number of LEDs in diagnostic function.
- Changes the LED behavior when LED device fails.
- Upgrades Debian version to 7.8.
- Work around solution for USB babble error.
- Disables micro SD "card detect" function.
- Builds watchdog driver into the kernel module.
- Turns off "Acquire::GzipIndexes" in the APT setting.

Notes

N/A



Version: v1.3	Build: Build 14112810
Release Date: N/A	

Applicable Products

UC-8100 Series

Supported Operating Systems

N/A

New Features

- Installs crda version 1.1.2-1.
- Installs firmware-ralink version 0.43~bpo70.
- Installs rfwkill version 0.4-1.
- Enables conntack kernel option.
- Enables LXC kernel option.

Enhancements

- Upgrades to Debian 7.7.
- Enhances the Wi-Fi connection utility.
- Adds signal and status function for cellular connections.
- Enables Spread Spectrum for CORE/PER/DDR.
- Adds Eth PHY analog off and power down function.
- Allows hardware assisted rts/cts modes to be disabled.
- Enhances stability of the SD driver.

Bugs Fixed

- System files issue.
- Security issue in OpenSSL.
- Security issue in bash.
- Sierra Wireless MC9090 issue.

Changes

- Update bootloader version to V1.1.
- Renames Wi-Fi utility from wifi.sh to wifi_mgmt.
- Use QMI instead of ppp to dial up Sierra Wireless MC73x4.
- Modifies SDRAM configuration to fit size and timing.
- Modifies GPIO_0_19 pin setting for EMI.
- Modifies MLO file check method in SD boot process.
- Use Wi-Fi open source driver instead of Ralink official driver.
- Disables USB PIO mode and enables USB DMA mode.

Notes

N/A



Version: v1.2	Build: Build 14080718
Release Date: N/A	

Applicable Products

UC-8100 Series

Supported Operating Systems

N/A

New Features

N/A

Enhancements

N/A

Bugs Fixed

- Backup zip file corrupted.

Changes

N/A

Notes

N/A



Version: v1.1	Build: Build 14072210
Release Date: N/A	

Applicable Products

UC-8100 Series

Supported Operating Systems

N/A

New Features

N/A

Enhancements

- Upgrades the package for OpenSSL.

Bugs Fixed

- Network driver issue.

Changes

- Removes the getty process.
- Disables GPS function for MC8090, MC9090.

Notes

N/A



Version: v1.0	Build: Build 14051515
Release Date: N/A	

Applicable Products

UC-8100 Series

Supported Operating Systems

N/A

New Features

- First release.

Enhancements

N/A

Bugs Fixed

N/A

Changes

N/A

Notes

N/A