

# Firmware for NPort IA5000 Series (hardware version 2.0 and later) Release Notes

Version: v2.1 Build: 22032321

Release Date: Mar 23, 2022

# **Applicable Products**

NPort IA5000 Series

**Supported Operating Systems** 

N/A

**New Features** 

N/A

**Enhancements** 

N/A

#### **Bugs Fixed**

• Fixed an issue where force transmission in Operation Mode does not work properly, Applicable Operation Modes include Real COM, TCP Server, TCP Client, UDP, and RFC2217.

## **Changes**

N/A

**Notes** 

N/A



Version: v2.0 Build: 21102111

Release Date: Oct 21, 2021

# **Applicable Products**

**NPort IA5000 Series** 

## **Supported Operating Systems**

N/A

#### **New Features**

• New firmware version for the NPort IA5000 Series V2 models.

#### **Enhancements**

N/A

# **Bugs Fixed**

N/A

# **Changes**

N/A

#### **Notes**

- The NPort IA5000 Series firmware v2.0 and later versions are incompatible with the older hardware versions of NPort IA5000 Series.
- Firmware v1.x can only be applied to NPort IA5000 Series hardware version V1.
- Firmware v2.x can only be applied to NPort IA5000 Series hardware version V2 and higher.



Version: v1.7 Build: Build 21032913

Release Date: Mar 31, 2021

## **Applicable Products**

**NPort IA5000 Series** 

## **Supported Operating Systems**

N/A

#### **New Features**

- Supports the MCC Tool.
- Added a notification regarding the limitation on the length of sensitive data.

#### **Enhancements**

Solved security issues: CVE-2017-16715, CVE-2017-14028, CVE-2017-16719, CVE-1999-0511.

## **Bugs Fixed**

- NPort might hang when using in a public network.
- NPort did not send SNMP Authentication Failure trap.
- Unable to get complete network info when max connection was full with NPort Fixed TTY driver.
- Force transmit time could work when it was set at 20 ms in UDP operation mode.
- The default gateway was invalid when the IP address ended with ".0".
- NPort sent a DUP ACK while handshaking.
- Saved configuration from the DHCP server to flash too frequently.

#### **Changes**

N/A

#### **Notes**

• This version of the firmware can be applied only to hardware version 1.x. Download firmware v2.x for NPort IA5000 Series hardware version V2 and higher.



Version: v1.6 Build: Build 17060616

Release Date: Jul 04, 2017

## **Applicable Products**

**NPort IA5000 Series** 

#### **Supported Operating Systems**

N/A

#### **New Features**

N/A

#### **Enhancements**

- Enhanced web login security and supports 5 users logged in simultaneously.
- Extended HTTP challenge ID length from 32 bits to 256 bits.
- Enabled the default password "moxa".
- Increased CSRF protection mechanism.
- Increased XSS protection mechanism.

# **Bugs Fixed**

- The user's password and SNMP community name may be exposed by a buffer overflow issue.
- NPort may reboot or hang from several buffer overflow attacks through Telnet, SSH, DSCI, SNMP, HTTP, and HTTPS.
- TCP/IP protocol may stop responding: CNCERT CNVD-2016-12094.
- In pair connection mode, master will not pull down RTS/DTR signal after the TCP connection is broken.

#### **Changes**

N/A

#### **Notes**

N/A